

SKU: **P31C**

30amp Plasma Cutter

- · Runs from a 13amp supply
- · 8mm clean cut on steel
- · HF Start for easy arc starting
- · High 35% duty cycle

The PLASMA 31C package includes a 4.5M plasma cutter torch, earth lead, air pressure regulator and PCL fitting, mains cable, owners manual and a torch consumables kit including tips, electrodes, gas distributors and shield cups.



SKU: P50HF

50amp Plasma Cutter

- · HF Pilot Arc Starting
- 18mm clean cut on steel
- · Easy torch fitting
- · High 60% duty cycle
- Low cost consumables

The PLASMA 50HF includes a 6m cutting torch, earth lead, air pressure regulator and PCL fitting, mains cable, owners manual and a torch consumables kit including 5x tips/electrodes.







Cuts Steel



Cuts Aluminium



24mm Max Cut



Cuts Steel



Cuts Aluminium

WHAT'S IN THE BOX?

4.5m plasma cutter torch, earth lead, mains cable, air pressure regulator and PCL fitting, owners manual, standard torch consumables kit - 5x tips/electrodes, 3x shield cups, 3x gas distributors.

TECHNICAL SPECIFICATIONS

30amps
30amps
15-30amps
13amps
12mm
8mm
6mm
Yes
Yes
Yes
Yes
100I/min
390x190x290
14kg

WHAT'S IN THE BOX?

6m LT70 plasma cutter torch, earth lead, mains cable, air pressure regulator and PCL fitting, owners manual.

TECHNICAL SPECIFICATIONS

TECHNICAE OF ECHTICATIONS	
Output @ 60% duty cycle	50amps
Input amperage	32amps
Genuine clean cut size mild steel	18mm
Genuine cut on alloy/stainless steel	13mm
Severance cut size on steel	24mm
HF pilot arc & re-start	Yes
LED amperage display	Yes
Generator friendly recommended size	8kVA
Industrial quality metal chassis	Yes
Thermostatic protection	Yes
Quick fit torch	Yes
Air consumption 3.45 bar 50psi	100I/min (3.5cfm)
Dimensions (mm)	390x190x290
Net weight	19kg